#### Landlords / Homeowner Gas Safety Record - G2



Gas-elec Group Summer Road, Walsham - Le - Willows, Bury St Edmunds, IP31 3AJ



Access Date: Friday, 15 May, 2020

Next expiry date: Tuesday, 18 May, 2021

Client:

Cert. No: CT-1151359-1522708001

Site Add.:

Gas Inspectior	s Inspection Details										
Meter Reading	Meter / ECV Location	AECV location (if app)	Meter Visual Inspection	Meter Type	ECV Accessible	Gas Installation Pipework	Let-By/Tightness Test	Record Pressure Drop	Protective Earth Bond		
03129	Kitchen Cupboard	N/A	Pass	SMART	Yes	Pass	Pass / Pass	0	Yes		

03129 Kitchen Cupboard		N/A	Pass	SMART	Yes	Pass		Pass / Pass 0		Yes
Gas Appliance Details		Fire/Back Boiler	Hob			Boiler/Combi				
Location		Living Room		Kitchen				Compartment		
Make		Baxi	Whirlpool			Vaillant				
Model #		Bermuda	AKM200/WH			ecoTec pro28 VUW GB 286/5-3 R2				
Serial #		-	49AR2014			21133200 100116901 30056095N4				
Flue Type		Open Flued	Flueless			Room S	Sealed			
Safety Device		N/C	N/P			Pass				
Operating Pres	ssure/Gas Rate	N/C	6 A V (NETT)	6 A V (NETT)			3.00 (NETT)			
Ventilation Ade	quate	N/C	ės	/ -s \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \			s Carrier and the second secon			
Flue Flow Test		N/C		I/A			A/A			
Spillage Test		N/C				N/A				
Termination Satisfactory		N/C	N/A			Yes				
Visual Condition		N/C	Pass			Pass				
Appliance Serviced		No	No			Yes				
ID, AR or Advis	sory entaction	N/A	N/A			N/A				
Gas Council No	amber	N/A	N/A			47-044-45				
Flue Gas Analysis (Ratio)		N/A - This appliance is not a boil	N/A - This appliance is not a boiler			0.0007				
Safe To Use		N/C		Yes			Yes			
Appliance relate	Appliance related comments:  The appliance previously disconnected / isolated from gas supply - unable to verify the point of disconnection. No inspection carried out			The hob burners do not have thermocouple safety devices (FSD), now a requirement for all hobs in flats - not to current standards.			No eng	gineer comment	ס	

In the event of a complaint relating to any service or installation in a property gas-elec must be given the opportunity to address the issue by re-visiting the property to resolve any alleged complaint. gas-elec cannot be held responsible if the opportunity to fully address the matter is not afforded to us. In the event of another company/contractor being called to the property to investigate or attempt to rectify an alleged complaint in preference to gas-elec the company will accept no liability. A detailed internal inspection of the flue integrity, construction and lining has not been carried out. I confirm that the situation(s) recorded above, has been identified and brought to the attention of the Responsible Person in

This report has been produced in accordance with the Gas-Elec Group working method statement which covers COVID -19 virus procedures.

A copy of this working method statement can be found on: <a href="https://www.gas-elec.co.uk/cvd19">www.gas-elec.co.uk/cvd19</a>

**Next Inspection Due Within 12 Months** 

(Please refer to 'General Comments' page for comments made by the engineer regarding the installation)

This Safety Record Issued By

### Landlords / Homeowner Gas Safety Record - G2



Gas-elec Group Summer Road, Walsham - Le - Willows, Bury St Edmunds, IP31 3AJ



Access Date: Friday, 15 May, 2020 Next expiry date: Tuesday, 18 May, 2021

Client:

Cert. No : CT-1151359-1522708001

Site Add.:

#### **General comments:**

The boiler is sited in the kitchen compartment. The flue is a concentric flue system. The flue rises vertically passing through the ceiling into the loft and roof to outside. The flue assembly in the loft has two support bracket fitted.

The carbon monoxide alarm was function tested and is working - expires Jun 2020.

SARVIPE

SARVIPE

Company of the carbon monoxide alarm was function tested and is working - expires Jun 2020.

## **Appliance Service Record**



Gas-elec Group Summer Road. Walsham - Le -Willows, Bury St Edmunds, IP31 3AJ



Date: Friday, 15 May, 2020

Client:

Cert. No: RP-1151359-1522708001

Faults found and rectification work

Site Add:

l	PPLIANCE										
	Location/Position	Туре	Type of Boiler	Make	Model	Flue Type	Serial No.	Gas Council Number	Approx. age		
	Kitchen Compartment	Boiler/Combi	Combi Boiler	Vaillant	ecoTec pro28 VUW GB	Room Sealed	21133200 100116901 30	247-044-45	6		

APPLIANCE CHECKLIST	Result	Rectification work necessary / completed	SAFETY TESTS	Faults found and rectific
Stability	Pass		Safety Device satisfactory?	Yes
Controls	Pass		Ventilation satisfactory?	Yes
ectrics	Pass		Flue flow test satisfactory?	N/A
ipework	Pass		Spillage test satisfactory?	N/A
ocation	Pass		Flue termination satisfactory?	Yes
askets/Seals	Pass	Replaced burner door seal.	Visual check satisfactory?	Yes
as Connections	Pass			
rner/Injectors	Pass	Cleaned	Tightness test satisfactory?	Yes
eaks Gas/Water	Pass		Op ng pr ure / gas sati ctory?	Yes
asing	Pass		C en ng pr ure / gas r reac g	6.00 kW (NETT)
nition	Pass			es
at Exchanger	Pass		Appli ce sat lo use?	es
Assembly	Pass			=5
ame Picture	N/A		FGA (Flue Gas Analysis) READINGS	
eturn air (warm air only)	N/A		CO (PPM): 64	
replace/Catchment	N/A		CO2 (%): 9.1	
verflow/Discharge	Pass	Condensate waste pump fitted.	CO/CO2 Ratio: 0.0007	
losure Plate	N/A		Engineer Comments	
opliance water flow	Pass		The condensate waste pipe is preventing the removal o	f the condensate sump for cleaning.
rate and temperature			, and the same of	,
Additional checks			The central heating timer selector switch on the boiler is	s missing/broken off.
completed				

In the event of a complaint relating to any service or installation in a property gas-elec must be given the opportunity to address the issue by re-visiting the property to resolve any alleged complaint, gas-elec cannot be held responsible if the opportunity to fully address the matter is not afforded to us. In the event of another company/contractor being called to the property to investigate or attempt to rectify an alleged complaint in preference to gas-elec the company will accept no liability. A detailed internal inspection of the flue integrity, construction and lining has not been carried out. I confirm that the situation(s) recorded above, has been identified and brought to the attention of the Responsible Person in accordance with the GSIUR, and Gas Industry Unsafe Situations Procedure. This report has been completed and issued by Gas-elec Safety (UK) Ltd.

Engineer name: Engineer signature:

This report has been produced in accordance with the Gas-Elec Group working method statement which covers COVID -19 virus procedures. A copy of this working method statement can be found on: www.gas-elec.co.uk/cvd19

# **Accompanying Photos**



Gas-elec Group Summer Road, Walsham - Le - Willows, Bury St Edmunds, IP31 3AJ 7PJ TEL: 0800 5879999 Job No.: 1522708

Date: 15/05/2020





#### Accompanying photos provided by the engineer

Description: CH timer plastic selector switch missing.



Description: Cooker hood filter panel missing.





The results shown on this report reflect the situation at the time of the inspection. Gas-Elec, its employees and engineers cannot be held responsible for any failure of the boiler or heating system after the inspection.

The report is a general visual, surface and functional examination of the central heating and / or plumbing system without risk of causing damage to the property or injury to the inspector. Due care is therefore exercised throughout the inspection regarding safety, practically and the constraints of being a visitor to the property (which may be occupied). Furniture, floor coverings and the contents are not moved or lifted and no part is forced or laid open to make accessible. Gas-elec Safety (UK) Ltd. or it's employees accept no liability for the consequences of any errors or omissions on this report.

Inspector:

Inspector Signature: