



SERVICE REPORT
ELECTRIC HOT WATER BOILERS

Customer / Client	Gas-elec Safety (UK) Ltd
Name	Summer Road,
Address	Walsham Le Willows,
.....	Bury St. Edmunds,
.....	IP31 3AJ
Postcode	Tel: 0800 587 9999
Tel	

APPLIANCE DETAILS	ELECTRICAL SUPPLY
Type Electric Boiler	Type 240 domestic
Make Caleffi	Tarif standard
Model Ista	Number Immersions 0
Serial No	Off Peak 0
Age 5	Timers 1

Engineer : Stewart **Date :** 10-Feb-2020 **Record No :** RP-5181253-1456953001

CHECK LIST	RESULT	Rectification Work Necessary / Completed
Supply Isolation Switches (1)	Pass	
Supply Isolation Switches (2)	Pass	
Supply Isolation Switches (3)	N/A	
Control Timer (1)	Pass	
Control Timer (2)	N/A	
Immersion 1 Connection	N/A	
Immersion 2 Connection	N/A	
Thermostat 1	Pass	
Thermostat 2	N/A	
Open Vent Expansion Tank	N/A	
Ball Valve	N/A	
Pressure Expansion Vessel	Pass	
Pressure Relief Valve	Pass	
T&P Relief Valve	N/A	
Motorised Valves	Pass	
Filters	Pass	
Pipe Connections	Pass	
Casing	Pass	
Labeling	Pass	
Anode	N/A	
Water Temperature	Pass	

SAMPLE

NOTES / OBSERVATIONS
tested and working correctly at this inspection

In the event of a complaint relating to any service or installation in a property gas-elec must be given the opportunity to address the issue by re-visiting the property to resolve any alleged complaint. gas-elec cannot be held responsible if the opportunity to fully address the matter is not afforded to us. In the event of another company/contractor being called to the property to investigate or attempt to rectify an alleged complaint in preference to gas-elec the company will accept no liability. 10/02/2020 00:00:00

DATE : Monday, February 10, 2020

ENGINEER SIGNATURE **ENGINEER PRINT NAME :**

Estimate ID: 283558

ESTIMATE



To:

From: Area 18
8-10 High Street
Billericay
Essex
CM12 9BQ

Tel: 01277 626399
Freephone: 0800 587 9999
Fax: 01277 626499
E-mail: area18@gas-elec.co.uk
Website: www.gas-elec.co.uk

Date: 11-Feb-2020

RE: _____

Dear ,

Thank you for the opportunity to provide an estimate for the remedial works at the above property. Following our survey at the property the following works are required:

Whilst on site other issues were highlighted which we have quoted on if you wish to address.

Shower rail is missing

Basin waste is blocked

Work required-

Recommend to supply and fit new shower rail

Clean out basin wastes

The work detailed above will cost £445.00 plus VAT @ 20% (Including parts and labour).

This estimate is valid for 28 days from the date shown above. If you have any questions or wish us to proceed please contact us at our office by Phone, Fax or Email.

Should you wish to accept this estimate, please call our office on 01277 626399 to schedule the remedial works. Also, please complete and return the Order Confirmation below.

gas-elec and all of the gas-elec engineers are registered with accreditation bodies and are qualified to carry out all types of gas & electrical remedial works. Gas-elec is also able to register work for building control purposes.

Yours sincerely,
Jenny Corby
Area 18

Estimate ID: 283558

ESTIMATE



Terms & Conditions

1. The estimate is valid for 28 days.
2. Work will only commence on receipt of a deposit of 50% of the value of the installation.
3. The estimate is for the works as detailed on the estimate letter. Any extra work will need to be paid for separately.
4. Work will commence on receipt of the signed order at the bottom of this estimate .
5. All work is guaranteed for 12 months from the date of installation.
6. Please note that if you choose to pay by credit card, you may be charged a fee for this method of payment. If you choose to pay by debit card, no additional charges will apply.

ORDER CONFIRMATION

I, _____, do hereby accept the estimate
(reference no.: _____) and agree to the Terms & Conditions listed above.

Signed: _____ Print name: _____

Address: _____

Post Code: _____

Daytime contact no.: _____

Email address: _____

SAMPLE



Accompanying Photos



Gas-elec Group
 Summer Road,
 Walsham - Le - Willows,
 Bury St Edmunds,
 IP31 3AJ 7PJ
 TEL : 0800 5879999

Job No.: 1456953

Date : 10/02/2020



Accompanying photos provided by the engineer

Description: Blocked basin



Description: Shower rail missing



SAMPLE

gas-elec

group

The results shown on this report reflect the situation at the time of the inspection. Gas-Elec, its employees and engineers cannot be held responsible for any failure of the boiler or heating system after the inspection.

The report is a general visual, surface and functional examination of the central heating and / or plumbing system without risk of causing damage to the property or injury to the inspector. Due care is therefore exercised throughout the inspection regarding safety, practically and the constraints of being a visitor to the property (which may be occupied). Furniture, floor coverings and the contents are not moved or lifted and no part is forced or laid open to make accessible. Gas-elec Safety (UK) Ltd. or it's employees accept no liability for the consequences of any errors or omissions on this report.

Inspector:

Inspector Signature: