

Annual Electrical Safety Record - E2



Gas-elec Group
 Summer Road,
 Walsham - Le - Willows,
 Bury St Edmunds,
 IP31 3AJ

Access Date: Tuesday, 26 May, 2020
 Next expiry date: Wednesday, 26 May, 2021

Cert. No: CT-0111492-1533493001

Client:

Site Add.:

INSTALLATION INSPECTION (Visual & Functional)

Electrical supply details		Meter Reading: 2,280
Type : TN-C-S	PIRE/ICR Label present Yes Expires on 26/05/2024	Meter Visual Inspection: Pass
Main Earthing Conductor	Main Protective Bonding Conductors	General Condition of Consumer Unit: Good
Present	Water : Yes Gas : Yes Other :	Consumer Unit Location: Cellar
		RCD Test: Yes
		RCD Operating times
		X1: 0.30 X5: 0.24
		Zs 0.37 Ω

Circuit Number	Description	Functional Check	Protective Device	Recommendations
1	Socket outlets Throughout	Yes	BS (EN) 61008	

APPLIANCE DETAILS/ ELECTRICAL EQUIPMENT RESULTS

ID	Location	Type	Make	Model	Serial	Body	Continuity (ohms)	Insulation (megohms)	Functional Check	Comments	Passed Safety Test
1	Kitchen	Dishwasher	Indesit	Unknown	n/f	N/Acc N/Acc Pass	0.27	0.01	Pass	Formal Visual Inspection	Yes
2	Kitchen	Oven	Sia	Unknown	n/f	N/Acc N/Acc Pass	0.27	0.01	Pass	Formal Visual Inspection	Yes
3	Kitchen	Hob	Sia	Unknown	n/f	N/Acc N/Acc Fail	N/C	N/C*	Pass	Formal Visual Inspection	Yes - VO
4	Kitchen	Cooker Hood	Sia	Chl61ss	n/f	N/Acc N/Acc Pass	0.35	0.01	Pass	Formal Visual Inspection	Yes
5	Kitchen	Washer Dryer	Hoover	Dynamic next	n/f	Pass Pass Pass	0.05	3.34	Pass	Formal Visual Inspection	Yes
6	Kitchen	Toaster	Russell Hobbs	Unknown	n/f	Pass Pass Pass	0.17	0.10	Pass	Formal Visual Inspection	Yes
7	Kitchen	Kettle	Russell Hobbs	25510	n/f	Pass Pass Pass	0.11	0.10	Pass	Formal Visual Inspection	Yes

Details of any faults found and rectification work necessary

Warning Notice

1		No	This Safety Record Issued By: Engineer Name:
2		No	
3	Glass cracked on front burner	No	
4		No	
5		No	
6		No	
7		No	

Next Inspection Due Within 12 Months

The report is a general, visual, surface and functional examination of the electrical system, which is accessible i.e. visible and readily available for inspection from ground and floor levels without risk of causing damage to the property or injury to the inspector and limited accordingly. Due care is therefore exercised throughout the inspection regarding safety, practicality and the constraints of being a visitor to the property (which may be occupied). So furniture, floor coverings and other contents are not moved, lifted and no part is forced or laid open to make it accessible. Loop impedance tests are only carried out on socket outlets. The report is provided solely for the use of the client and no liability to anyone else is accepted. Should the client not act upon specific advice contained in the report, no responsibility is accepted for the consequences. Gas-elec Safety (UK) Ltd, its employees or franchisees accept no liability for the consequences of any errors or omissions in this report. **THIS IS A VISUAL AND FUNCTIONAL INSPECTION ONLY.** In the event of a complaint relating to any service or installation in a property gas-elec must be given the opportunity to address the issue by re-visiting the property to resolve any alleged complaint. gas-elec cannot be held responsible if the opportunity to fully address the matter is not afforded to us. In the event of another company/contractor being called to the property to investigate or attempt to rectify an alleged complaint in preference to gas-elec the company will accept no liability. Where passed safety test is VO, this is an abbreviation of visual only inspection. **This report has been produced in accordance with the Gas-Elec Group working method statement which covers COVID -19 virus procedures. A copy of this working method statement can be found on: www.gas-elec.co.uk/cvd19**

Annual Electrical Safety Record - E2



Gas-elec Group
 Summer Road,
 Walsham - Le - Willows,
 Bury St Edmunds,
 IP31 3AJ

Access Date: Tuesday, 26 May, 2020
 Next expiry date: Wednesday, 26 May, 2021

Cert. No: CT-0111492-1533493001

Client:

Site Add.:

INSTALLATION INSPECTION (Visual & Functional)

Electrical supply details		Meter Reading: 2,280
Type : TN-C-S	PIR/EICR Label present Yes Expires on 26/05/2024	Meter Visual Inspection: Pass
Main Earthing Conductor	Main Protective Bonding Conductors	General Condition of Consumer Unit: Good
Present	Water : Yes Gas : Yes Other :	Consumer Unit Location: Cellar
		RCD Test: Yes
		RCD Operating times
		X1: 0.30 X5: 0.24
		Zs 0.37 Ω

Circuit Number	Description	Functional Check	Protective Device	Recommendations
----------------	-------------	------------------	-------------------	-----------------

APPLIANCE DETAILS/ ELECTRICAL EQUIPMENT RESULTS

ID	Location	Type	Make	Model	Serial No.	Fuse	Body	Continuity (ohms)	Insulation (megohms)	Functional Check	Comments	Passed Safety Test	
8	Kitchen	Microwave	Russell Hobbs	Unknown		Pass	Pass	Pass	0.06	0.32	Pass	Normal Visual Inspection	Yes
9	Kitchen	Fridge/Freezer	Hisense	Unknown		Pass	Pass	Pass	0.10	0.14	Pass	Normal Visual Inspection	Yes
10	Kitchen	Iron	Morphy richards	300274	n/f	Pass	Pass	Pass	19.99	0.10	Pass	Normal Visual Inspection	Yes

Details of any faults found and rectification work necessary

Warning Notice

8	No	This Safety Record Issued By:
9	No	
10	No	
		Engineer Name:

Next Inspection Due Within 12 Months

The report is a general, visual, surface and functional examination of the electrical system, which is accessible i.e. visible and readily available for inspection from ground and floor levels without risk of causing damage to the property or injury to the inspector and limited accordingly. Due care is therefore exercised throughout the inspection regarding safety, practicality and the constraints of being a visitor to the property (which may be occupied). So furniture, floor coverings and other contents are not moved, lifted and no part is forced or laid open to make it accessible. Loop impedance tests are only carried out on socket outlets. The report is provided solely for the use of the client and no liability to anyone else is accepted. Should the client not act upon specific advice contained in the report, no responsibility is accepted for the consequences. Gas-elec Safety (UK) Ltd, its employees or franchisees accept no liability for the consequences of any errors or omissions in this report. **THIS IS A VISUAL AND FUNCTIONAL INSPECTION ONLY.** In the event of a complaint relating to any service or installation in a property **gas-elec** must be given the opportunity to address the issue by re-visiting the property to resolve any alleged complaint. **gas-elec** cannot be held responsible if the opportunity to fully address the matter is not afforded to us. In the event of another company/contractor being called to the property to investigate or attempt to rectify an alleged complaint in preference to **gas-elec** the company will accept no liability. Where passed safety test is VO, this is an abbreviation of visual only inspection. **This report has been produced in accordance with the Gas-Elec Group working method statement which covers COVID -19 virus procedures. A copy of this working method statement can be found on: www.gas-elec.co.uk/cvd19**

Accompanying Photos



Gas-elec Group
 Summer Road,
 Walsham - Le - Willows,
 Bury St Edmunds,
 IP31 3AJ 7PJ
 TEL : 0800 5879999

Job No.: 1533493

Date : 26/05/2020



Accompanying photos provided by the engineer

Description: Cracked hob



SAMPLE

gas-elec

group

The results shown on this report reflect the situation at the time of the inspection. Gas-Elec, its employees and engineers cannot be held responsible for any failure of the boiler or heating system after the inspection.

The report is a general visual, surface and functional examination of the central heating and / or plumbing system without risk of causing damage to the property or injury to the inspector. Due care is therefore exercised throughout the inspection regarding safety, practically and the constraints of being a visitor to the property (which may be occupied). Furniture, floor coverings and the contents are not moved or lifted and no part is forced or laid open to make accessible. Gas-elec Safety (UK) Ltd. or it's employees accept no liability for the consequences of any errors or omissions on this report.

Inspector:

Inspector Signature: